

# USB 3.1 ENGINEERING CHANGE NOTICE

**Title: Figure 5-4 Dimensional Correction**

**Applies to: USB 3.1 Legacy Cable and Connector Specification, Revision 1.0**

<b>Brief description of the functional changes proposed:</b>
The 1.68 dimension in Section M-M of Figure 5-4 was accidentally moved from Datum A to the plug overmold during the implementation of ECN 014. This change restores the figure to illustrate the dimension correctly. <u><b>This is an editorial correction.</b></u>

<b>Benefits as a result of the proposed changes:</b>
Corrects the implementation of ECN 014 and aligns the specification figure to match the critical dimension requirement called out in the compliance specification.

<b>An assessment of the impact to the existing revision and systems that currently conform to the USB specification:</b>
N/A

<b>An analysis of the hardware implications:</b>
N/A


<b>An analysis of the software implications:</b>
N/A

<b>An analysis of the compliance testing implications:</b>
Existing compliance documentation is already correct with regard to this dimensioning – no impact or change required.

# USB 3.1 ENGINEERING CHANGE NOTICE



## Actual Change Requested

From Text: Section 5.3.1.1, Figure 5-4, Page 18




To Text: Section 5.3.1.1, Figure 5-4, Page 18


# USB 3.1 ENGINEERING CHANGE NOTICE



SECTION P-P




SECTION T-T



SECTION M-M

ALL INSERTION/WITHDRAWAL FORCES MUST BE MAINTAINED



SECTION Q-Q